

Work Completion Browse

Labour	Contractor	WO_No	Task	Qty	Rate	Amount	WC_Date	Pay_Schedule	PS_Percent	Remark	RA_Bill_No	Approve_Amount	Approve_Date	Balanced	Executed_By
GANGA DHAM TOWERS															
L Groove - BCV	R K INTERIOR	1707	A 3002 Master Toilet dado-(No.)	20.0000	141.7500	2835.0000000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	-120011.3700000000	R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 3002 Parents Toilet dado-(No.)	30.0000	141.7500	4252.5000000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	-118593.8700000000	R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 3002 Powder Toilet dado-(No.)	26.0000	141.7500	3685.5000000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	-119160.8700000000	R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 3002 Staff Toilet dado-(No.)	10.0000	141.7500	1417.5000000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	-121428.8700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 2701 Staff Toilet dado-(No.)	115.0000	70.8750	8150.6250000000	18/08/2024 14:59:00	Labour Charges for 600 x 300mm Dado Fixing work for staff toilet.	100.00000		109958	122846.3700	01/01/1900	-114695.7450000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 2903 Master Toilet dado-(No.) - 1 No.	120.0000	70.8750	8505.0000000000	18/08/2024 14:42:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-114341.3700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 2903 Powder Toilet dado-(No.) - 1 No.	80.0000	70.8750	5670.0000000000	18/08/2024 14:42:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-117176.3700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Children Toilet-(No.)	143.0000	70.8750	10135.1250000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-112711.2450000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Dry Balcony dado-(No.)	82.8300	70.8750	5870.5762500000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-116975.7937500000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Master Toilet dado-(No.)	100.0000	70.8750	7087.5000000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-115758.8700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Parents Toilet dado-(No.)	120.0000	70.8750	8505.0000000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-114341.3700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Powder Toilet dado-(No.)	70.0000	70.8750	4961.2500000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 600mm Dado	100.00000		109958	122846.3700	01/01/1900	-117885.1200000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 2903 Master Toilet dado-(No.) - 1 No.	60.0000	70.8750	4252.5000000000	18/08/2024 14:42:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-118593.8700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 2903 Powder Toilet dado-(No.) - 1 No.	30.0000	70.8750	2126.2500000000	18/08/2024 14:42:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-120720.1200000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Children Toilet-(No.)	35.0000	70.8750	2480.6250000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-120365.7450000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Master Toilet dado-(No.)	60.0000	70.8750	4252.5000000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-118593.8700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Parents Toilet dado-(No.)	80.0000	70.8750	5670.0000000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-117176.3700000000	R K INTERIOR
Dado BC	R K INTERIOR	1707	A 3002 Powder Toilet dado-(No.)	40.0000	70.8750	2835.0000000000	18/08/2024 15:04:00	Labour Charges for Fixing of 600 x 1200mm Dado	100.00000		109958	122846.3700	01/01/1900	-120011.3700000000	R K INTERIOR
Vitrified Flooring -BC	R K INTERIOR	1707	A 3002 A 102 Children Toilet Vitrified Flooring	52.2900	33.0750	1729.4917500000	18/08/2024 14:18:00	Labour Charges for Vitrified flooring work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	-121116.8782500000	R K INTERIOR
Vitrified Flooring -BC	R K INTERIOR	1707	A 3002 A 102 Master Toilet Vitrified Flooring	45.0000	33.0750	1488.3750000000	18/08/2024 14:18:00	Labour Charges for Vitrified flooring work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	-121357.9950000000	R K INTERIOR
Vitrified Flooring -BC	R K INTERIOR	1707	A 3002 A 102 Parents Toilet Vitrified Flooring	50.0000	33.0750	1653.7500000000	18/08/2024 14:18:00	Labour Charges for Vitrified flooring work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	-121192.6200000000	R K INTERIOR

Labour	Contractor	WO_No	Task	Qty	Rate	Amount	WC_Date	Pay_Schedule	PS_Percent	Remark	RA_Bill_No	Approve_Amount	Approve_Date	Balanced	Executed_By
Vitrified Flooring -BC	R K INTERIOR	1707	A 3002 A 102 Powder Toilet Vitrified Flooring	36.2790	33.0750	1199.9279250000	18/08/2024 14:18:00	Labour Charges for Vitrified flooring work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	121646.4420750000	- R K INTERIOR
Vitrified Flooring -BC	R K INTERIOR	1707	A 3002 A 102 Staff Toilet Vitrified Flooring	20.0000	33.0750	661.5000000000	18/08/2024 14:18:00	Labour Charges for Vitrified flooring work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	122184.8700000000	- R K INTERIOR
Vitrified Skirting BC	R K INTERIOR	1707	A 3002 A 102 Balcony Vitrified Flooring	40.0000	33.0750	1323.0000000000	18/08/2024 14:18:00	Labour Charges for Vitrified Skirting work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	121523.3700000000	- R K INTERIOR
Vitrified Skirting BC	R K INTERIOR	1707	A 3002 A 102 Kitchen Vitrified Flooring	25.2560	33.0750	835.3422000000	18/08/2024 14:18:00	Labour Charges for Vitrified Skirting work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	122011.0278000000	- R K INTERIOR
Vitrified Skirting BC	R K INTERIOR	1707	A 3002 A 102 Staff Room Vitrified Flooring	15.0000	33.0750	496.1250000000	18/08/2024 14:18:00	Labour Charges for Vitrified Skirting work for A Building internal Flat area with proper line,level,right angle and joint filling.	100.00000		109958	122846.3700	01/01/1900	122350.2450000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 2903 Children Toilet dado-(No.)- (No.) - 1 No.	40.0000	141.7500	5670.0000000000	18/08/2024 14:42:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	117176.3700000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 2903 Dry Balcony dado-(No.) - 1 No.	5.0000	141.7500	708.7500000000	18/08/2024 14:42:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	122137.6200000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 2903 Guest Toilet dado-(No.) - 1 No.	28.0000	141.7500	3969.0000000000	18/08/2024 14:42:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	118877.3700000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 2903 Master Toilet dado-(No.) - 1 No.	40.0000	141.7500	5670.0000000000	18/08/2024 14:42:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	117176.3700000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 2903 Powder Toilet dado-(No.) - 1 No.	4.5000	141.7500	637.8750000000	18/08/2024 14:42:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	122208.4950000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 3002 Children Toilet-(No.)	25.0000	141.7500	3543.7500000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	119302.6200000000	- R K INTERIOR
L Groove - BCV	R K INTERIOR	1707	A 3002 Dry Balcony dado-(No.)	4.0000	141.7500	567.0000000000	18/08/2024 15:04:00	Labour Charges for L Groove work in vitrified tile for A Building Dado.	100.00000		109958	122846.3700	01/01/1900	122279.3700000000	- R K INTERIOR